



This classification was made using seven indicators developed to provide a scope for measuring how adequate the dwellings are. The following features were assessed: Space(min18m2/HH), durability (period of intended use), drainage, ventilation, ceiling height, privacy, security and accessibility.



Percentage of Totally Inadequate and Inadequate Dwelling by Province:



Dwelling Adequacy Classification

- Fairly Inadequate
- Fairly Adequate
- Adequate
- Inadequate

✓ Distance of 50 Km from Yolanda
⚡ Typhoon Path

Data sources:
National Boundaries: OCHA
Damage Data: Reach
Coordinate System: GCS WGS 1984
File: REACH_PHL_Report_ShelterClusterAssessment AdequacyLevels_05Sep2014_ENG
Contact: reach.mapping@impact-initiatives.org

Note: Data, designations and boundaries contained on this map are not warranted to error-free and do not imply acceptance by the REACH partners, associated, donors mentioned on this map.